TEST RESULTS




Ford Mustang Standard Safety Equipment



🛧 습 습 습





2017

SPECIFICATION

Tested Model	Ford Mustang 5.0 Fastback, LHD
Body Type	- 2 door coupe
Year Of Publication	2017
Kerb Weight	1768kg
VIN From Which Rating Applies	- all Mustang Fastbacks
Class	Roadster sports

General comments

This assessment of the Ford Mustang is based on the vehicle that has been on sale since 2015. Ford has informed Euro NCAP that orders placed after May will receive an updated vehicle, which will be launched later in 2017, and will be equipped with Pre Collision Assist (with Pedestrian Detection, Forward Collision Warning and Autonomous Emergency Braking) and Lane Keeping Aid.



SAFETY EQUIPMENT

	Driver	Passenger	Rear
FRONTAL CRASH PROTECTION			
Frontal airbag	•	•	—
Belt pretensioner	•	•	×
Belt loadlimiter	•	•	×
Knee airbag	•	•	
SIDE CRASH PROTECTION			
Side head airbag	•	•	•
Side chest airbag	•	•	×
Side pelvis airbag	•	•	×
CHILD PROTECTION			
Isofix		×	•
Integrated CRS		×	×
Airbag cut-off switch		•	
SAFETY ASSIST			
Seat Belt Reminder	•	•	×

OTHER SYSTEMS	
Active Bonnet (Hood)	•
AEB City	×
AEB Inter-Urban	×
Speed Assistance System	×
Lane Assist System	×


Note: Other equipment may be available on the vehicle but was not considered in the test year.

Fitted to the vehicle as standard

O Not fitted to the test vehicle but available as option or as part of the safety pack

🗙 Not available 🛛 🗕 Not applicable







Version 230117




<u> ADULT OCCUPANT</u>

Total 27.7 Pts / 72%


Comments

The passenger compartment of the Mustang remained stable in the frontal offset test. Dummy readings indicated good protection of the knees and femurs of the driver and passenger dummies. Analysis of the dummy data showed that the driver's head had 'bottomed out' the airbag i.e. there was insufficient pressure in the airbag to prevent the head from contacting the steering wheel through the deflated airbag material. The head of the passenger dummy also bottomed out the airbag against the dashboard, owing to insufficient inflation of the airbag and inadequate restraint for larger statures by the front passenger seatbelt load-limiter. The scores of both the driver and passenger were penalised for the airbag performance. In the full-width rigid barrier test, protection of the driver was good apart from the chest, protection of which was adequate. However, the rear seat passenger slipped under the lap portion of the seatbelt (a phenomenon known as 'submarining') and the score for the knee, femur and pelvis body region was penalised and protection was rated as poor. Protection of the chest was also rated as poor as the rear seatbelt (which has neither pre-tensioners nor load-limiters) showed an excessively high tensile force in the test. Dummy readings of head deceleration indicated weak protection of the head for the rear passenger. In the side barrier test, the Mustang scored full points with good protection of all critical body areas. Even in the more severe side pole test, protection of the chest was adequate and that of other body regions was good. Tests on the front seats and head restraints demonstrated a marginal level of protection against whiplash injury in the event of a rear-end collision. A geometric assessment of rear seats indicated poor whiplash protection in these seating positions. The current Mustang is not equipped with an autonomous emergency braking (AEB) system, which would have provided greater whiplash protection. However, Ford have indicated that the next version of the Mustang will have AEB.



Restraint for 6 year old child: Britax-Römer KidFix XP
Restraint for 10 year old child: Booster cushion
Safety Features

0 Pts





😉 CHILD OCCUPANT

Total 15.8 Pts / 32%

ISOFIX CRS



Römer KidFix XP (ISOFIX)



Universal Belted CRS



Römer KidFix XP (Belt)





Römer King II LS (Belt)



BeSafe iZi Kid X4 ISOfix (ISOFIX)







💪 CHILD OCCUPANT


Total 15.8 Pts / 32%

	Sea	Seat Position	
	Front	2nd row	
	PASSENGER	LEFT	RIGHT
Maxi Cosi 2way Pearl & 2wayFix (rearward) (iSize)			
Maxi Cosi 2way Pearl & 2wayFix (forward) (iSize)			
BeSafe iZi Kid X2 i-Size (iSize)			
Maxi Cosi Cabriofix & FamilyFix (ISOFIX)			•
BeSafe iZi Kid X4 ISOfix (ISOFIX)		×	×
Römer Duo Plus (ISOFIX)	D		۲
Römer KidFix XP (ISOFIX)	D		•
Maxi Cosi Cabriofix (Belt)	•	•	•
Maxi Cosi Cabriofix & EasyBase2 (Belt)	•	•	•
Römer King II LS (Belt)	•	•	•
Römer KidFix XP (Belt)	•		•

Comments

For the impact tests, the 10 year dummy was sat on a booster cushion. Owing to limited rear space the results of the dynamic tests on the 10 year dummy were done in a separate test. In the frontal offset test, protection of the 10 year dummy was rated as at least adequate. However, the shoulder belt slipped between the clavicle and the upper arm and the score for the dummy in this test was penalised. Protection of the 6 year dummy, sat in a high-back booster, was rated as good and adequate for the head and neck respectively but dummy readings of chest deceleration indicated marginal chest protection. In the side barrier test, dummy readings indicated good protection, apart from the head of the 10 year dummy. The head bottomed out the side curtain airbag, making contact, through the deflated airbag material, with the trim on the C pillar. Consequently, all points were lost for the 10 year dummy in this test. The front passenger airbag can be disabled to allow a rearward-facing restraint to be used in that seating position. However, information provided to the driver regarding the status of the airbag did not meet Euro NCAP's requirements and the system did not score any points.






AEB Pedestrian

Comments

The Mustang has an 'active' bonnet. Sensors in the bumper detect when a pedestrian has been struck and actuators lift the bonnet, creating more space to the hard structures in the engine bay. Ford demonstrated that the system worked robustly for a variety of pedestrian statures and over a range of speeds and, accordingly, the tests were performed in the raised (deployed) position. Test results were good over almost the entire bonnet surface. Protection of the pelvic region was poor in all areas tested but the bumper provided good protection to pedestrians' legs and scored maximum points in Euro NCAP's tests. There is no AEB system on the current Mustang but Ford have indicated that the next version of the Mustang will have one.

0 Pts







SAFETY ASSIST

Total 2 Pts / 16%

Comments

The Mustang has a seatbelt reminder system for the front seats only and no other safety assistance features that qualify for points in Euro NCAP's rating scheme. Ford have indicated that the successor to the current Mustang will be equipped with AEB.



RATING VALIDITY

Variants of Model Range

Body Type	Engine & Transmission Model Name/Code		Drivetrain	Rating Applies	
				LHD	RHD
* 2 door coupe	5.0 V8 Manual and Automatic	Mustang Fastback 5.0 V8	4 X 2	~	~
2 door coupe	2.3 EcoBoost Manual and Automatic	Mustang Fastback 2.3 EcoBoost	4 X 2	~	~
2 door convertible	5.0 V8 Manual and Automatic	Mustang Convertible 5.0 V8	4 X 2	×	×
2 door convertible	2.3 EcoBoost Manual and Automatic	Mustang Convertible 2.3 EcoBoost	4 X 2	×	×

* Tested variant

Annual Reviews and Facelifts

Date	Event	Outcome
January 2017	Rating Published	2017 🛨 🛨 🟠 🏠 🖌